

**Case History: Archbishop John Carroll High School**  
*Full renovation of 1200 telescopic bleacher seats in high school recreation center*  
*Wayne Bleachers retrofitted with Century Design® system*



Ferguson Recreation Center at Archbishop John Carroll High School in Radnor, PA.



Bleachers on one side of recreation center are eight rows high. Opposite bank of bleachers is fourteen rows high.



First step is to remove the fir lumber from the bleachers for refinishing at Bleacherman's facility. The understructure (manufactured by Wayne) was repaired and serviced.



The existing footboards were replaced with code-compliant footboards. Existing heelboards were refinished in the same color as the footboards.



Sections were unanchored and re-aligned to eliminate gaps between sections. Motors were installed in conjunction with rigid row ties.



After being planed, edged, sanded and receiving three coats of approved sealer, seatboards and risers are reinstalled with new hardware



A unique feature found on Wayne bleachers are these manual horizontal and vertical adjustment screws. These are not available in new bleacher systems.



When you see this label, it means these bleacher will not sag. Period.



Fully refinished to "as new" condition with the Century Design no-sag system and with all safety equipment installed. Note the even row spacing across the entire bank.



Sometimes using the bleachers in the partially open position is required. It's no problem when bleachers have the Century Design® system installed.



Safety rails, P-rails and ADA wheelchair spaces always available in school colors at no extra charge.



The owner's representative stated he really liked the figure and grain of the wood after it was refinished. Savings versus buying new bleachers was approximately 30%.